

NYG 1163142

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple.

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD000224956303002</b>		Manifest Doc. No.	2. Page 1 of 1	Information within heavy bold line is not required by Federal Law.		
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>				A. <b>NYG 1163142</b>				
4. Generator's Telephone Number (732) 321-4427				B. Generator's ID <b>SAME</b>				
5. Transporter 1 (Company Name) <b>Freehold Cartage</b>		6. US EPA ID Number <b>NYD054126164</b>		C. State Transporter's ID <b>04-40411 ME</b>		D. Transporter's Telephone (732) 462-1001		
7. Transporter 2 (Company Name)		8. US EPA ID Number		E. State Transporter's ID		F. Transporter's Telephone ( )		
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>		10. US EPA ID Number <b>NYD094736679</b>		G. State Facility ID		H. Facility Telephone ( ) <b>716-854-9231</b>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)				12. Containers	13. Total	14. Unit	I. Waste No.	
a. <b>RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>				Number	Type	Quantity		Wt/Vol
b.								EPA
c.								STATE
d.								EPA
J. Additional Descriptions for Materials listed Above				K. Handling Codes for Wastes Listed Above				
a. <b>CW4538: ERG#171</b>				a. <input type="checkbox"/>				
b.				b. <input type="checkbox"/>				
15. Special Handling Instructions and Additional Information <b>Emergency - 732 540-8730 ; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR# 683363-7 1-2043</b>								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.								
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>				Signature <i>Jack Harmon</i>				
17. Transporter 1 Acknowledgement of Receipt of Materials				Mo. Day Year <b>06/04/03</b>				
Printed/Typed Name <b>Eric Bixby</b>				Signature <i>Eric Bixby</i>				
18. Transporter 2 Acknowledgement of Receipt of Materials				Mo. Day Year <b>06/04/03</b>				
Printed/Typed Name				Signature				
19. Discrepancy Indication Space								
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.								
Printed/Typed Name				Signature				
				Mo. Day Year				

250082



NYG 1163142

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NY000224956303002</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of Information within heavy bold line is not required by Federal Law.	
3. Generator's Name and Mailing Address <b>AT&amp;T Jack Harmon USEPA Region II - Rossett Manufacturing 2390 Woodbridge Ave., Edison, NJ 08837</b>				A. <b>NYG 1163142</b>			
4. Generator's Telephone Number <b>(732) 321-4427</b>		5. Transporter 1 (Company Name) <b>Freehold Cartage</b>		6. US EPA ID Number <b>NJ0054126164</b>		B. Generator's ID <b>NAME</b>	
7. Transporter 2 (Company Name)		8. US EPA ID Number		C. State Transporter's ID		D. Transporter's Telephone <b>(732) 452-1001</b>	
9. Designated Facility Name and Site Address <b>CMI Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>		10. US EPA ID Number <b>NY0094736679</b>		E. State Transporter's ID		F. Transporter's Telephone ( )	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>a. 20, Waste Polychlorinated biphenyle, solid mixture, 9, UN 2315, PG II</b>				12. Containers Number Type <b>001 CM</b>		13. Total Quantity <b>100000</b>	
				14. Unit Wt/Vol <b>KG</b>		I. Waste No. EPA <b>STATE 8007</b>	
J. Additional Descriptions for Materials listed Above <b>a. CM4538; 2258171 1. B</b>				K. Handling Codes for Wastes Listed Above <b>a. L</b>			
b.				b.			
c.				c.			
d.				d.			
15. Special Handling Instructions and Additional Information <b>Emergency - 732 542-0720; Send copy of completed manifest &amp; CD to Dawn Blavins, 8473 Huaka Rd., Stony Creek, VA 23892</b> <b>Date out of Service: 5/19/02 SR# 483313-7 1-20-12</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>Jack Harmon, USEPA Region II</b>				Signature <i>Jack Harmon</i> Mo. Day Year <b>06 09 03</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name <i>Jack Harmon</i>				Signature <i>Jack Harmon</i> Mo. Day Year <b>06 09 03</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name				Signature Mo. Day Year			
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name				Signature Mo. Day Year			

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

# FREEHOLD CARTAGE INC.

P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924



175 BARTOW MUN. AIRPORT  
BARTOW, FL 33830  
PHONE: (941) 533-4599  
FAX: (941) 533-1613

108 MONAHAN AVENUE  
DUNMORE, PA 18512  
PHONE: (570) 342-7232  
FAX: (570) 342-7367

350 PIGEON POINT ROAD  
NEW CASTLE, DE 19720  
PHONE: (302) 658-2005  
FAX: (302) 658-6229

156 DRIFTWOOD DRIVE  
EUTAWVILLE, SC 29048  
PHONE/FAX: (803) 492-9595

## MANIFEST

FCI EPA ID NO.:  
NJD054126164

**K 58445**

GENERATOR NAME/ADDRESS <b>BOECCOTT MFG. USEPA Region II</b> <b>OTICA NY 13502</b>		PHONE (AREA CODE) <b>732-341-4427</b> TRACTOR <b>567</b> TRAILER <b>294</b>		GENERATOR EPA ID NO. <b>040002249583</b>	
FCI REP. LOADING (PRINT) <b>Eric P. V. V.</b>		PROCEDURE <b>Removal</b>		APPOINTMENT TIME :	
COMMENTS OR DELAYS AT GENERATOR		BOX SPOTTED		BOX REMOVED <b>0001</b>	
				TIME AT GENERATOR (MILITARY TIME ONLY) <b>16:30</b>	
				ARRIVAL TIME DEPARTURE TIME	
				EQUIPMENT USED	

BROKER:		STATE MANIFEST NO.:									
PO#:		WO#:									
(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM	
1	<b>Soc. 1000 #</b>	<b>9</b>	<b>3.5.1</b>	<b>TL</b>	<b>1</b>	<b>CA</b>	<b>20</b>	<b>YD</b>	<b>107</b>		
2	<b>PCB</b>										
3											

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION (I.E., IDENTIFICATION SHIPMENT OF A NON-HAZARDOUS NATURE WHICH DOES NOT HAVE TO BE MANIFESTED).

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The wastes described above were consigned to the Transported named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste, and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the generator is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvestad IET</b>	GENERATOR'S SIGNATURE <b>X Kim Alvestad</b> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED MO. / DAY / YR.
--	---	--------------------------------

TSDF NAME/ADDRESS <b>Cwm</b> <b>MODEL CITY NY 14107</b>		PHONE (AREA CODE) <b>716-754-8231</b> TRACTOR TRAILER		TSDF EPA ID NO. <b>0400094736679</b>	
FCI REP. UNLOADING (PRINT)		PROCEDURE <b>Dump</b>		APPOINTMENT TIME :	
COMMENTS OR DELAYS AT TSDF		BOX SPOTTED		BOX REMOVED	
				TIME AT TSDF (MILITARY TIME ONLY) :	
				ARRIVAL TIME DEPARTURE TIME	
				EQUIPMENT USED	
PLEASE PRINT NAME/TITLE		TSDF SIGNATURE <b>X</b>		DATE UNLOADED MO. / DAY / YR.	

AR H-0257  
PC 944

CT CT-HW-307

DE DE-HW-203

DE-SW-203

IL SWH-1540

ME ME-HWT-47

ME-WOT-47

MD HWH-167

96-OP-1765

MA MA-294

MN 61572

MO H-1490

ND WH-429

NH TNH-0047

NJ S-2265

15939

NY NJ-113

NOVA SCOTIA, CANADA NSC 000 147

OH UPW-0190713-OH

OK 3358

ONTARIO, CANADA A 840943

PA PA-AH-0067

QUEBEC, CANADA QC-6ML-047

RI RI-535

TX 40705

WI 11602

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator

**K 58445**

NYG 1163133

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD002249563030011</b>		Manifest Doc. No.		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>NYG 1163133</b>					
4. Generator's Telephone Number (732) 321-4427											
5. Transporter 1 (Company Name) <b>Freehold Cartage</b>			6. US EPA ID Number <b>NJD054126164</b>			C. State Transporter's ID <b>65062/4462</b>					
7. Transporter 2 (Company Name)			8. US EPA ID Number			D. Transporter's Telephone (732) 462-1001					
9. Designated Facility Name and Site Address <b>CWM Chemical Waste Services 1135 Balmer Rd. Model City, NY 14107</b>			10. US EPA ID Number <b>NYD094736679</b>			E. State Transporter's ID					
						F. Transporter's Telephone ( )					
						G. State Facility ID					
						H. Facility Telephone ( ) <b>716-754-8231</b>					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit	
						Number		Quantity		Wt/Vol	
a. <b>RO, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>						001 CM		10000		K	
b.										I. Waste No. EPA	
c.										STATE <b>B007</b>	
d.										EPA	
										STATE	
										EPA	
										STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. <b>CW4538; ERC#171</b>						a. <input type="checkbox"/>					
b.						b. <input type="checkbox"/>					
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8730 ; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR# 683363-6 1-20 yd3</b>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>						Signature <i>Jack Harmon</i>					
						Mo. Day Year <b>06 04 03</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name <b>Michael L. Cummings</b>						Signature <i>Michael L. Cummings</i>					
						Mo. Day Year <b>06 04 03</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name						Signature					
						Mo. Day Year					
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name						Signature					
						Mo. Day Year					

**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362		
FACILITY	TRANSPORTER	GENERATOR

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**N16845**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-736740 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <b>U.S. E.P.A. BOSSERT Mfg UTICA, N.Y. 13502</b>		PHONE (AREA CODE) <b>65002</b>		TRAILER <b>4462</b>		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT) <b>Michael L. Cumming</b>		PROCEDURE <b>REMOVAL</b>		EQUIP. SPOTTED		EQUIP. REMOVED <b>9467</b>	
TIME AT SHIPPER :		TIME AT SHIPPER :		TIME AT SHIPPER :		TIME AT SHIPPER :	
ARRIVAL TIME		ARRIVAL TIME		ARRIVAL TIME		ARRIVAL TIME	
DEPARTURE TIME		DEPARTURE TIME		DEPARTURE TIME		DEPARTURE TIME	
COMMENTS OR DELAYS AT SHIPPER		COMMENTS OR DELAYS AT SHIPPER		COMMENTS OR DELAYS AT SHIPPER		COMMENTS OR DELAYS AT SHIPPER	
EQUIPMENT USED		EQUIPMENT USED		EQUIPMENT USED		EQUIPMENT USED	

BROKER:		MANIFEST / DOCUMENT NO.	
PO #:	WO#:		

(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	SEE ATTACHED	9	2315 II	001	cm	10,000	k	0007		
2	MANIFEST									
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER	
--	--

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvestad / ET</b>	SHIPPER'S SIGNATURE X <b>Kim Alvestad</b> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <b>06/04/03</b> MO. DAY YEAR
---	---	--

CONSIGNEE NAME/ADDRESS <b>CWM</b>		PHONE (AREA CODE) <b>65002</b>		TRAILER <b>4462</b>		APPOINTMENT TIME :	
FCI REP. UNLOADING (PRINT) <b>Michael L. Cumming</b>		PROCEDURE <b>Dump</b>		EQUIP. SPOTTED		EQUIP. REMOVED <b>9467</b>	
TIME AT CONSIGNEE :		TIME AT CONSIGNEE :		TIME AT CONSIGNEE :		TIME AT CONSIGNEE :	
ARRIVAL TIME		ARRIVAL TIME		ARRIVAL TIME		ARRIVAL TIME	
DEPARTURE TIME		DEPARTURE TIME		DEPARTURE TIME		DEPARTURE TIME	
COMMENTS OR DELAYS AT CONSIGNEE		COMMENTS OR DELAYS AT CONSIGNEE		COMMENTS OR DELAYS AT CONSIGNEE		COMMENTS OR DELAYS AT CONSIGNEE	
EQUIPMENT USED		EQUIPMENT USED		EQUIPMENT USED		EQUIPMENT USED	
PLEASE PRINT NAME/TITLE		CONSIGNEE SIGNATURE X _____		DATE UNLOADED / / MO. DAY YEAR			

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**N16845**

**-HERKIMER SOLID WASTE AUTHORITY**1600 Genesee Street, Utica, NY 13502  
(315) 733-1224 FAX (315) 733-2305**585584**

TICKET NUMBER

99

594677

**B  
I  
L  
L  
T  
O**ONEIDA/HERKIMER RESIDENT  
CASH CUSTOMER  
CASH CUSTOMER  
CASH CUSTOMER NY**H  
A  
U  
L  
E  
R**99U12  
UTICA CASH VEHICLE

Scale 2 Scale 2

DATE	ENTRY TIME	OPER.	EXIT TIME	OPER.	GROSS WEIGHT	TARE WEIGHT	NET WEIGHT
6/4/2003	15:48:14	JAYNE	15:48:17		579001b	01b	579001b 28.95 tons
					Inbound	Outbound	

QUANTITY	MATERIAL CODE	DESCRIPTION/ORIGIN	UNITS	UNIT PRICE	AMOUNT
28.95 EA	WEIGHT	VEHICLE WEIGHT	EA	10.00	10.00

1.00 # units (if used)

I hereby certify that the information provided on this form is true to the best of my knowledge.

RIVER NAME

PRINT SIGNATURE

**DOCUMENT  
TOTAL**

10.00

# NYG 1163151

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303003</b>		Manifest Doc. No.		2. Page 1 of 1		Information within heavy bold-line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						A. <b>NYG 1163151</b>					
4. Generator's Telephone Number (732) 321-4427						B. Generator's ID <b>SAME</b>					
5. Transporter 1 (Company Name) <b>Freehold Cartage Inc</b>						C. State Transporter's ID <b>0440516 hf</b>					
6. US EPA ID Number <b>NYD0541126164</b>						D. Transporter's Telephone (732) 462-1001					
7. Transporter 2 (Company Name)						E. State Transporter's ID					
8. US EPA ID Number						F. Transporter's Telephone ( )					
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balme Rd. Model City, NY 14107</b>						G. State Facility ID					
10. US EPA ID Number <b>NYD094736679</b>						H. Facility Telephone ( )					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit	
						Number		Quantity		Wt/Vol	
a. <b>RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>						<b>1</b>		<b>EST</b>		<b>Kg</b>	
						<b>0 021 C M</b>		<b>1 000 0</b>			
b.										I. Waste No.	
										EPA	
										STATE <b>B007</b>	
c.										EPA	
										STATE	
d.										EPA	
										STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. <b>CW4538; ERG1171</b>						a. <input type="checkbox"/>					
b.						b. <input type="checkbox"/>					
c.						c. <input type="checkbox"/>					
d.						d. <input type="checkbox"/>					
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8730; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd. Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR # 683363-8 1-20yd<sup>3</sup></b>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>						Signature <i>Jack Harmon</i>					
Mo. <b>06</b> Day <b>04</b> Year <b>03</b>											
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name <b>Wayne Y. Jones</b>						Signature <i>Wayne Y. Jones</i>					
Mo. <b>06</b> Day <b>04</b> Year <b>03</b>											
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name						Signature					
Mo. Day Year											
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name						Signature					
Mo. Day Year											

GENERATOR

TRANSPORTER

FACILITY



NYG 1163151

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. NY000224956303003		Manifest Doc. No. 1		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.					
3. Generator's Name and Mailing Address <b>US EPA Region II - Bussert Manufacturing</b> <b>2890 Woodbridge Ave., Edison, NJ 08837</b>						A. <b>NYG1163151</b>							
4. Generator's Telephone Number (732) 321-4427						B. Generator's ID SAME							
5. Transporter 1 (Company Name) <b>Freehold Cartage Z</b>						C. State Transporter's ID 0448516							
6. US EPA ID Number NJ00054126164						D. Transporter's Telephone (732) 452-1001							
7. Transporter 2 (Company Name)						E. State Transporter's ID							
8. US EPA ID Number						F. Transporter's Telephone ( )							
9. Designated Facility Name and Site Address <b>CMS Chemical Services, Inc.</b> <b>1135 Balco Rd.</b> <b>Model City, NJ 14107</b>						G. State Facility ID							
10. US EPA ID Number NY00094736679						H. Facility Telephone ( ) 716-754-8231							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers Number Type		13. Total Quantity		14. Unit Wt/Vol		I. Waste No.	
a. <b>80. Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>						0 011 CM		2.5 T		Kg		EPA STATE 5507	
b.												EPA STATE	
c.												EPA STATE	
d.												EPA STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above							
a. <b>CW4538; BRG1171</b>						a. <input checked="" type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/> d. <input type="checkbox"/>							
b.						b. <input type="checkbox"/> d. <input type="checkbox"/>							
15. Special Handling Instructions and Additional Information <b>Emergency - 283 543 - 2122; Send copy of completed manifest &amp; CD to Dawn Slavias,</b> <b>8473 Huske Rd. Stony Creek, VA 23082</b> <b>Date out of Service: 5/19/02 SL # 101343-X 1-20 yls</b>													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.													
Printed/Typed Name <b>Jack Hannon, US EPA Region II OSC</b>						Signature <i>Jack Hannon</i>		Mo. Day Year 10 4 04 05					
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name <i>W. Hannon</i>		Signature <i>W. Hannon</i>		Mo. Day Year 10 6 04 03			
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name		Signature		Mo. Day Year			
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						Printed/Typed Name		Signature		Mo. Day Year			

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362



# FREEHOLD CARTAGE INC.

P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924

**BILL OF LADING**  
FCI EPA ID NO. NJD054126164

**N 46463**

114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984

350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229

175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-1613

5533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732

108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-7367

40 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <b>Bossett Manufacturing</b> <b>Edison NJ</b> <b>Union NY 13500</b>		PHONE <b>732</b> (AREA CODE) <b>321-4407</b>		N 4 0 0 0 2 2 4 9 5 6 3	
FCI REP. LOADING (PRINT) <b>Wagner Lenger</b>		PROCEDURE <b>Removal</b>	EQUIP. SPOTTED	EQUIP. REMOVED <b>9944</b>	APPOINTMENT TIME :
COMMENTS OR DELAYS AT SHIPPER		EQUIPMENT USED			

BROKER:		MANIFEST / DOCUMENT NO. <b>NY 67163151</b> <b>03003</b>									
PO #:		WO#:									
(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM	
1	<b>See Manifest</b>										
2											
3											

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvestad / ET</b>	SHIPPER'S SIGNATURE X <b>[Signature]</b> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <b>6 / 4 / 03</b> MO. DAY YEAR
---	--	--

CONSIGNEE NAME/ADDRESS <b>Cam</b> <b>Madison City NY 14107</b>		PHONE <b>716</b> (AREA CODE) <b>754-8231</b>		M 4 0 0 9 4 7 3 6 6 7 9	
FCI REP. UNLOADING (PRINT)		PROCEDURE	EQUIP. SPOTTED	EQUIP. REMOVED	APPOINTMENT TIME :
COMMENTS OR DELAYS AT CONSIGNEE		EQUIPMENT USED			
PLEASE PRINT NAME/TITLE		CONSIGNEE SIGNATURE X _____			DATE UNLOADED / / MO. DAY YEAR

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator

**N 46463**

# NYG 1163169

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



## HAZARDOUS WASTE MANIFEST P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No.		Manifest Doc. No.		2. Page 1 of		Information within heavy bold line is not required by Federal Law.																							
		NYD00224956303004		1		1																									
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon</b> <b>USEPA Region II - Bossert Manufacturing</b> <b>2890 Woodbridge Ave., Edison, NJ 08837</b>		4. Generator's Telephone Number (732 ) <b>321-4427</b>		5. Transporter 1 (Company Name) <b>Freehold Cartage INC.</b>		6. US EPA ID Number <b>NJD054126164</b>		7. Transporter 2 (Company Name)		8. US EPA ID Number		9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc.</b> <b>1135 Balmer Rd.</b> <b>Model City, NY 14107</b>		10. US EPA ID Number <b>NYD094736679</b>		A. <b>NYG 1163169</b>		B. Generator's ID <b>SAME</b>		C. State Transporter's ID <b>0444349 ME</b>		D. Transporter's Telephone <b>732 462-1001</b>		E. State Transporter's ID		F. Transporter's Telephone ( )		G. State Facility ID		H. Facility Telephone ( ) <b>716-754-8231</b>	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)  a. <b>RO, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>		12. Containers Number		13. Total Quantity		14. Unit Wt/Vol		I. Waste No.		EPA		STATE		B007		EPA		STATE		EPA		STATE		EPA		STATE					
J. Additional Descriptions for Materials listed Above  a. <b>CW4538; ERG#171</b>		K. Handling Codes for Wastes Listed Above		a		b		c		d		e		f		g		h		i		j		k		l					
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8730; Send copy of completed manifest &amp; Cd to Dawn Blevins,</b> <b>8473 Huske Rd., Stony Creek, VA 23802</b> <b>Date out of Service: 5/9/03 SR # 6833639 1-20 yd<sup>3</sup></b>		16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.		Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>		Signature <i>Jack Harmon</i>		Mo. Day Year <b>06 04 03</b>		17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name <b>ROBERT SMITH</b>		Signature <i>Robert Smith</i>		Mo. Day Year <b>06 04 03</b>		18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		Mo. Day Year							
19. Discrepancy Indication Space		20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name		Signature		Mo. Day Year																							

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

GENERATOR

TRANSPORTER

FACILITY

NYG 1163169

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NY000224956303004</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of Information within heavy bold line is not required by Federal Law.																			
3. Generator's Name and Mailing Address <b>ATTN: Jack Hanson USEPA Region II - Consort Manufacturing 2690 Woodbridge Ave., Edison, NJ 08837</b>				<div style="border: 2px solid black; padding: 5px; text-align: center; font-size: 1.2em; font-weight: bold;">NYG 1163169</div>																					
4. Generator's Telephone Number <b>(732) 321-4427</b>		6. US EPA ID Number <b>NY0054126154</b>																							
5. Transporter 1 (Company Name) <b>Prachold Cartage</b>		8. US EPA ID Number																							
7. Transporter 2 (Company Name)		10. US EPA ID Number <b>NY0054735679</b>																							
9. Designated Facility Name and Site Address <b>Chem Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>		H. Facility Telephone <b>716-754-8231</b>																							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>a. RG, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2315, PG II</b>				12. Containers Number Type <b>001 CH</b>		13. Total Quantity <b>10000</b>																			
				14. Unit Wt/Vol <b>K</b>		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td colspan="2">I. Waste No.</td></tr> <tr><td>EPA</td><td></td></tr> <tr><td>STATE</td><td><b>2907</b></td></tr> <tr><td>EPA</td><td></td></tr> <tr><td>STATE</td><td></td></tr> <tr><td>EPA</td><td></td></tr> <tr><td>STATE</td><td></td></tr> <tr><td>EPA</td><td></td></tr> <tr><td>STATE</td><td></td></tr> </table>		I. Waste No.		EPA		STATE	<b>2907</b>	EPA		STATE		EPA		STATE		EPA		STATE	
I. Waste No.																									
EPA																									
STATE	<b>2907</b>																								
EPA																									
STATE																									
EPA																									
STATE																									
EPA																									
STATE																									
J. Additional Descriptions for Materials listed Above <b>a. CH4538; ERG171</b>				K. Handling Codes for Wastes Listed Above <b>a. 1</b>																					
b.				b.																					
c.				c.																					
d.				d.																					
15. Special Handling Instructions and Additional Information <b>Emergency - 212-541-4100 Send copy of completed manifest &amp; CD to Dawn Blovinz, 8473 Buske Rd., Stony Creek, VA 23382</b> <b>Date out of Service: 5/9/02 SIC # 4833637</b>																									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.																									
Printed/Typed Name <b>Jack Hanson, USEPA Region II OSC</b>				Signature <i>Jack Hanson</i>																					
17. Transporter 1 Acknowledgement of Receipt of Materials				Mo. Day Year <b>06 04 03</b>																					
Printed/Typed Name <i>Robert Smith</i>				Signature <i>Robert Smith</i>																					
18. Transporter 2 Acknowledgement of Receipt of Materials				Mo. Day Year																					
Printed/Typed Name				Signature																					
19. Discrepancy Indication Space																									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.																									
Printed/Typed Name				Signature																					
				Mo. Day Year																					

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**L 74857**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-7367156 Driftwood Drive  
Eutawville, SC 29048  
Phone: (803) 492-9595  
Fax: (803) 492-3350

SHIPPER NAME/ADDRESS <b>DOSSSEPT MANIF</b>		PHONE <b>732-321-4427</b>		APPOINTMENT TIME <b>11/06/02 249563</b>	
LOCATION NY.		(AREA CODE)			
TRACTOR <b>748</b>		TRAILER <b>4445</b>		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT) <b>Bob Smith</b>	PROCEDURE <b>REMOVE</b>	EQUIP. SPOTTED	EQUIP. REMOVED <b>0308</b>	TIME AT SHIPPER <b>16:00</b>	(MILITARY TIME ONLY) <b>17:00</b>
COMMENTS OR DELAYS AT SHIPPER				ARRIVAL TIME	DEPARTURE TIME
				EQUIPMENT USED	

BROKER:		<b>MANIFEST / DOCUMENT NO. 10/61163169</b>
PO #:	WO #:	

(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	SEE MANIFEST	9	2315	II	1	CM	2.4			S
2										
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER.
---

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvordstad/ET.</b>	SHIPPER'S SIGNATURE <b>X</b> <i>[Signature]</i> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <b>6/14/03</b> MO. DAY YR.
--	---	--

CONSIGNEE NAME/ADDRESS <b>CUM</b>		PHONE			
		(AREA CODE)			
MODEL CITY, NY		TRACTOR <b>748</b>		TRAILER <b>4445</b>	
				APPOINTMENT TIME :	
FCI REP. UNLOADING (PRINT) <b>Bob Smith</b>	PROCEDURE	EQUIP. SPOTTED	EQUIP. REMOVED	TIME AT CONSIGNEE :	(MILITARY TIME ONLY) :
COMMENTS OR DELAYS AT CONSIGNEE				ARRIVAL TIME	DEPARTURE TIME
				EQUIPMENT USED	

PLEASE PRINT NAME/TITLE	CONSIGNEE SIGNATURE <b>X</b> _____	DATE UNLOADED <b>6/15/03</b> MO. DAY YR.
-------------------------	---------------------------------------	--

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK 3358	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**L 74857**

# NYG 1163178

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



## HAZARDOUS WASTE MANIFEST P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No: <b>NYD00224956303005</b>		Manifest Doc. No. <b>1</b>	2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.	
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon</b> <b>USEPA Region II - Bossert Manufacturing</b> <b>3890 Woodbridge Ave., Edison, NJ 08837</b> 4. Generator's Telephone Number <b>(732) 321-4427</b> 5. Transporter 1 (Company Name) <b>Freehold Cartage Inc</b> 6. US EPA ID Number <b>NYD054126164</b> 7. Transporter 2 (Company Name) _____ 8. US EPA ID Number _____ 9. Designated Facility Name and Site Address <b>CWN Chemical Services, Inc.</b> <b>1135 Balmer Rd.</b> <b>Model City, NY 14107</b> 10. US EPA ID Number <b>NYD094736679</b>					<b>A. NYG 1163178</b> <b>B. Generator's ID</b> <b>SAME</b> <b>C. State Transporter's ID</b> <b>ME0470754</b> <b>D. Transporter's Telephone</b> <b>(732) 462-1001</b> <b>E. State Transporter's ID</b> _____ <b>F. Transporter's Telephone</b> ( ) _____ <b>G. State Facility ID</b> _____ <b>H. Facility Telephone</b> ( ) <b>716-754-8231</b>			
					11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>00, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b> 12. Containers Number Type <b>001CM</b> 13. Total Quantity <b>EST 10000</b> 14. Unit Wt/Vol <b>Kg</b> I. Waste No. EPA <b>B007</b> STATE _____ EPA _____ STATE _____ EPA _____ STATE _____			
J. Additional Descriptions for Materials listed Above <b>a CW4538; ERG#171 1+3 c</b> <b>b d</b>					K. Handling Codes for Wastes Listed Above <b>a c</b> <b>b d</b>			
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8730; Send copy of completed manifest &amp; Cd to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR # 1023363-10 1-2043</b>								
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford. Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b> Signature <i>Jack Harmon</i> Mo. <b>06</b> Day <b>04</b> Year <b>03</b>								
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>John Romagosa-Jice</b> Signature <i>John Romagosa-Jice</i> Mo. <b>06</b> Day <b>04</b> Year <b>03</b>								
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name _____ Signature _____ Mo. _____ Day _____ Year _____								
19. Discrepancy Indication Space _____								
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name _____ Signature _____ Mo. _____ Day _____ Year _____								

NYG 1163178

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224955303005</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of 1 Information within heavy bold-line is not required by Federal Law.	
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon US EPA Region II - Borsart Manufacturing 3830 Woodbridge Ave., Edison, NJ 08837</b>				A. <b>NYG 1163178</b>			
4. Generator's Telephone Number (732) 321-4427		6. US EPA ID Number <b>NYD0054126164</b>		C. State Transporter's ID		B. Generator's ID	
5. Transporter 1 (Company Name) <b>Freehold Cartage, Inc.</b>		8. US EPA ID Number		D. Transporter's Telephone (732) 462-1001		E. State Transporter's ID	
7. Transporter 2 (Company Name)		10. US EPA ID Number <b>NYD0094736679</b>		F. Transporter's Telephone ( )		G. State Facility ID	
9. Designated Facility Name and Site Address <b>CMI Chemical Services, Inc. 1135 Palmer Rd. Model City, NY 14107</b>		H. Facility Telephone ( ) <b>716-754-9231</b>					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>a. 20, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>				12. Containers Number Type <b>001 CM</b>		13. Total Quantity <b>10000</b>	
				14. Unit <b>K</b>		I. Waste No. <b>EPA STATE 5007</b>	
J. Additional Descriptions for Materials listed Above <b>a. CM4530; EIGH171 1.3</b>				K. Handling Codes for Wastes Listed Above <b>a. L</b>			
b.				b.			
c.				c.			
d.				d.			
15. Special Handling Instructions and Additional Information: <b>Emergency - 732-462-8320; Send copy of completed manifest &amp; Cd to Sam Slovins, 8473 Suske Rd., Stony Creek, VA 22082 Date out of Service: 5/9/03</b>							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.							
Printed/Typed Name <b>Jack Harmon, US EPA Region II OSC</b>				Signature <i>Jack Harmon</i>		Mo. Day Year <b>06 04 03</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials							
Printed/Typed Name <i>Jack Harmon</i>				Signature <i>Jack Harmon</i>		Mo. Day Year <b>06 04 03</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials							
Printed/Typed Name				Signature		Mo. Day Year	
19. Discrepancy Indication Space							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.							
Printed/Typed Name				Signature		Mo. Day Year	

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**N 43027**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-736740 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <i>B-32257 Monahan</i>		PHONE <i>732-321-4427</i>			
		(AREA CODE)			
TRACTOR <i>507</i>		TRAILER <i>341</i>		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT) <i>John R. Monahan</i>		PROCEDURE <i>Removal</i>		EQUIP. SPOTTED <i>00137</i>	
		EQUIP. REMOVED		TIME AT SHIPPER (MILITARY TIME ONLY) <i>16:00</i>	
				ARRIVAL TIME :	
COMMENTS OR DELAYS AT SHIPPER				DEPARTURE TIME	
				EQUIPMENT USED	

BROKER:		MANIFEST / DOCUMENT NO.									
PO #:		WO#:									
(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM	
1	<i>See Manifest</i>	<i>9</i>	<i>2315</i>	<i>II</i>	<i>1</i>	<i>CM</i>	<i>20</i>	<i>X</i>			
2											
3											

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER										

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <i>Kim Alves tal / ET</i>		SHIPPER'S SIGNATURE <i>X [Signature]</i>		DATE LOADED <i>6 19 03</i>	
		I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.		MO. DAY YEAR	

CONSIGNEE NAME/ADDRESS		PHONE			
		(AREA CODE)			
TRACTOR		TRAILER		APPOINTMENT TIME :	
FCI REP. UNLOADING (PRINT)		PROCEDURE		EQUIP. SPOTTED	
		EQUIP. REMOVED		TIME AT CONSIGNEE (MILITARY TIME ONLY) :	
				ARRIVAL TIME :	
COMMENTS OR DELAYS AT CONSIGNEE				DEPARTURE TIME	
				EQUIPMENT USED	

PLEASE PRINT NAME/TITLE		CONSIGNEE SIGNATURE <i>X _____</i>		DATE UNLOADED <i>/ /</i>	
				MO. DAY YEAR	

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**N 43027**



NYG 1163187

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No.: <b>NYD00224956303006</b>		Manifest Doc. No.: <b>1</b>		2. Page 1 of <b>1</b>		Information within heavy bold line is not required by Federal Law.							
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163187</b> <b>B. Generator's ID SAME</b> <b>C. State Transporter's ID 0440515 smc</b> <b>D. Transporter's Telephone (732) 462-1001</b> <b>E. State Transporter's ID</b> <b>F. Transporter's Telephone ( )</b> <b>G. State Facility ID</b> <b>H. Facility Telephone ( ) 716-754-8231</b>									
4. Generator's Telephone Number <b>(732) 321-4427</b>		6. US EPA ID Number <b>NYD054126164</b>		7. Transporter 1 (Company Name) <b>Freehold Carriage Inc</b>						8. US EPA ID Number <b>NYD094736679</b>					
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>															
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers Number Type		13. Total Quantity		14. Unit Wt/Vol		I. Waste No.			
a. <b>RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>						0 0 1 C M		<b>EST 10000</b>		<b>Kg</b>		EPA <b>STATE 0007</b>			
b.												EPA STATE			
c.												EPA STATE			
d.												EPA STATE			
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above									
a. <b>CW4538; ERG1171</b>						a. <input type="checkbox"/> c. <input type="checkbox"/>									
b.						b. <input type="checkbox"/> d. <input type="checkbox"/>									
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8330; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882 Date out of Service: 5/9/03</b> <b>SR# 683363-11 1-20 yd<sup>3</sup></b>															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.															
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>						Signature <i>Jack Harmon</i>		Mo. <b>06</b>		Day <b>04</b>		Year <b>2003</b>			
17. Transporter 1 Acknowledgement of Receipt of Materials						Printed/Typed Name <b>DAVE OMROD</b>		Signature <i>Dave Omrod</i>		Mo. <b>6</b>		Day <b>16</b>		Year <b>2003</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials						Printed/Typed Name		Signature		Mo.		Day		Year	
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.															
Printed/Typed Name						Signature		Mo.		Day		Year			

GENERATOR

TRANSPORTER

FACILITY

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

NYG 1163187

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. NYD00224956303006	Manifest Doc. No. 1	2. Page 1 of 1	Information within heavy bold line is not required by Federal Law.
3. Generator's Name and Mailing Address USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837			A. NYG 1163187		
4. Generator's Telephone Number (732) 321-4427			B. Generator's ID		
5. Transporter 1 (Company Name) Frederick Carriage Inc.			C. State Transporter's ID		
6. US EPA ID Number NJ0054126164			D. Transporter's Telephone (732) 452-1901		
7. Transporter 2 (Company Name)			E. State Transporter's ID		
8. US EPA ID Number			F. Transporter's Telephone ( )		
9. Designated Facility Name and Site Address C&S Chemical Services, Inc. 1135 Balmer Rd. Rosal City, NY 14107			G. State Facility ID		
10. US EPA ID Number NYD094736679			H. Facility Telephone (716) 754-9231		
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers Number Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. RO, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II		001 CA	100000	1	EPA 8007 STATE 8007
b.					EPA STATE
c.					EPA STATE
d.					EPA STATE
J. Additional Descriptions for Materials listed Above			K. Handling Codes for Wastes Listed Above		
a. CH4530; EPC1171			a. <input checked="" type="checkbox"/> b. <input type="checkbox"/> c. <input type="checkbox"/>		
b.			b. <input type="checkbox"/> d. <input type="checkbox"/>		
15. Special Handling Instructions and Additional Information Emergency - 1-800-233-2733 Send copy of completed manifest & CD to Dave Blavins, 8473 Rustle Rd., Stony Creek, VA 23082 Date out of Service: 5/19/02					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name Jack Baran, USEPA Region II OSC		Signature [Signature]		Mo. Day Year 06 07 02	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Mo. Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Mo. Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Mo. Day Year	

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**N 47705**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-736740 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <i>PERMIT TO</i> <i>UTICA AIR 13502</i>		PHONE <i>732-321-4427</i> (AREA CODE) TRACTOR <i>719</i> TRAILER <i>404</i>		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT)	PROCEDURE <i>1/1A</i>	EQUIP. SPOTTED <i>1722</i>	EQUIP. REMOVED	TIME AT SHIPPER <i>14:00</i>	(MILITARY TIME ONLY) <i>18:42</i>
COMMENTS OR DELAYS AT SHIPPER <i>11/10/00 4/10/00 1/1</i>				ARRIVAL TIME DEPARTURE TIME	
EQUIPMENT USED					

BROKER:		MANIFEST / DOCUMENT NO. <i>116 H63157</i>	
PO #:	WO#:		

(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	<i>see manifest</i>	<i>7</i>	<i>2310</i>	<i>253</i>	<i>01</i>	<i>CM</i>	<i>1000</i>	<i>kg</i>	<i>007</i>	<i>5</i>
2										
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER										
--	--	--	--	--	--	--	--	--	--	--

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <i>Kim Alvstad / ET</i>		SHIPPER'S SIGNATURE X <i>Kim Alvstad</i> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.		DATE LOADED <i>6/11/03</i> MO. DAY YEAR	
--	--	--	--	---	--

CONSIGNEE NAME/ADDRESS <i>COM</i> <i>Model City Air 14117</i>		PHONE <i>716-754-8231</i> (AREA CODE) TRACTOR TRAILER		APPOINTMENT TIME :	
FCI REP. UNLOADING (PRINT)	PROCEDURE	EQUIP. SPOTTED	EQUIP. REMOVED	TIME AT CONSIGNEE :	(MILITARY TIME ONLY) :
COMMENTS OR DELAYS AT CONSIGNEE				ARRIVAL TIME DEPARTURE TIME	
EQUIPMENT USED					

PLEASE PRINT NAME/TITLE		CONSIGNEE SIGNATURE X _____		DATE UNLOADED / / MO. DAY YEAR	
-------------------------	--	--------------------------------	--	--------------------------------------	--

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**N 47705**

NYG 1163196

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No.		Manifest Doc. No.		2. Page 1 of		Information within heavy bold line is not required by Federal Law.			
		NYD00224956303007									
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon</b> USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837						A. <b>NYG 1163196</b>					
										4. Generator's Telephone Number (732) 321-4427	
5. Transporter 1 (Company Name)			6. US EPA ID Number			C. State Transporter's ID					
Freehold Cartage Inc			NJ D054126164			D. Transporter's Telephone (732) 462-1001					
7. Transporter 2 (Company Name)			8. US EPA ID Number			E. State Transporter's ID					
						F. Transporter's Telephone ( )					
9. Designated Facility Name and Site Address			10. US EPA ID Number			G. State Facility ID					
CWM Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107			NYD094736679			H. Facility Telephone ( ) 716-754-8231					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit	
						Number Type		Quantity		Wt/Vol	
a. RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II						2				I. Waste No.	
						DDCM				K	
b.						10/2/02				EPA	
c.										STATE B007	
d.										EPA	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
						a. CW4539; RRC#171					
b.						b. <input type="checkbox"/> d. <input type="checkbox"/>					
15. Special Handling Instructions and Additional Information											
Emergency - 732 548-8730; Send copy of completed manifest & CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23382 Date out of services: 5/9/03 SR#683363-1 1-30yd <sup>3</sup> 1-20yd <sup>3</sup>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name				Signature				Mo. Day Year			
Jack Harmon, USEPA Region II OSC				<i>Jack Harmon</i>				06 03 03			
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name				Signature				Mo. Day Year			
MICHAEL L. Cummings				<i>Michael L. Cummings</i>				06 03 03			
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name				Signature				Mo. Day Year			
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name				Signature				Mo. Day Year			

GENERATOR

TRANSPORTER

FACILITY

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

NYG 1163196



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303007</b>	Manifest Doc. No. <b>1</b>	2. Page 1 of	Information within heavy bold line is not required by Federal Law.
3. Generator's Name and Mailing Address <b>USEPA Region II - Sossart Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837 732 321-4427</b>			A. <b>NYG 1163196</b>		
4. Generator's Telephone Number			B. Generator's ID <b>Same</b>		
5. Transporter 1 (Company Name) <b>Freehold Cartage Inc</b>			C. State Transporter's ID <b>15-2/4912</b>		
6. US EPA ID Number <b>NYD054126154</b>			D. Transporter's Telephone (732) <b>462-1001</b>		
7. Transporter 2 (Company Name)			E. State Transporter's ID		
8. US EPA ID Number			F. Transporter's Telephone ( )		
9. Designated Facility Name and Site Address <b>CMI Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>			G. State Facility ID		
10. US EPA ID Number <b>NYD094736679</b>			H. Facility Telephone ( ) <b>716-754-8231</b>		
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers Number Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a. <b>HQ, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2315, PG II</b>		<b>001 CB</b>		<b>L</b>	EPA STATE <b>2307</b>
b.					EPA STATE
c.					EPA STATE
d.					EPA STATE
J. Additional Descriptions for Materials listed Above		K. Handling Codes for Wastes Listed Above			
a. <b>CM4539; 5200171</b>		c. <b>E</b>		<input type="checkbox"/>	
b.		d.		<input type="checkbox"/>	
15. Special Handling Instructions and Additional Information <b>Emergency - 711 472 3721 Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Hanks Rd., Stony Creek, VA 23882 Data out of service: 5/19/03 SRF 62263-1 1-5041 1-40113</b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name <b>Jack Baran, USEPA Region II OSC</b>		Signature <i>Jack Baran</i>		Mo. Day Year <b>06 03 03</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name <i>Michael L. Robinson</i>		Signature <i>Michael L. Robinson</i>		Mo. Day Year <b>06 03 03</b>	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Mo. Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Mo. Day Year	



Manifest #  
1163196

# FREEHOLD CARTAGE INC.

P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924

BILL OF LADING  
FCI EPA ID NO. NJD054126164

N16843

114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984

350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229

175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-1613

5533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732

108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-7367

40 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <b>USEPA BOSSERT MFG. UTICA, N.Y. 13502</b>		PHONE (AREA CODE) <b>65002</b>		TRAILER <b>4462</b>		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT) <b>Michael L. Cummings</b>		PROCEDURE <b>REMOVAL</b>		EQUIP. SPOTTED <b>0018</b>		EQUIP. REMOVED <b>9706</b>	
COMMENTS OR DELAYS AT SHIPPER						EQUIPMENT USED	

BROKER:				MANIFEST / DOCUMENT NO.							
PO #:				WO#:							
(X) HM	PROPER U.S. D.O.T. SHIPPING NAME		U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	SEE ATTACHED		9	2315	11	002CM			K	8007	
2	MANIFEST										
3											

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvestad</b>		SHIPPER'S SIGNATURE X <b>[Signature]</b>		DATE LOADED <b>6/3/03</b>	
		I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.		MO. DAY YEAR	

CONSIGNEE NAME/ADDRESS <b>CHEM WASTE</b>		PHONE (AREA CODE)		TRAILER <b>4462</b>		APPOINTMENT TIME :	
FCI REP. UNLOADING (PRINT) <b>Michael L. Cummings</b>		PROCEDURE <b>Dump</b>		EQUIP. SPOTTED <b>0018</b>		EQUIP. REMOVED <b>9706</b>	
COMMENTS OR DELAYS AT CONSIGNEE						EQUIPMENT USED	
PLEASE PRINT NAME/TITLE				CONSIGNEE SIGNATURE X _____		DATE UNLOADED / /	
						MO. DAY YEAR	

AR H-0257.	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator

N16843

NYG 1163214

DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



Please type or print. Do not staple

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303009</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of 1		Information within heavy bold-line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163214</b> <b>B. Generator's ID</b> <b>SAME</b> <b>C. State Transporter's ID</b> <i>OH 40416 ME</i> <b>D. Transporter's Telephone</b> (732) 462-1001 <b>E. State Transporter's ID</b> <b>F. Transporter's Telephone</b> ( ) <b>G. State Facility ID</b> <b>H. Facility Telephone</b> ( ) 716-754-8231					
4. Generator's Telephone Number (732) 321-4427		6. US EPA ID Number <b>NYD054126164</b>									
5. Transporter 1 (Company Name) <b>Frechold Cartage Inc</b>		8. US EPA ID Number									
7. Transporter 2 (Company Name)		10. US EPA ID Number <b>NYD094736679</b>									
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balmer Rd., Model City, NY 14107</b>											
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers Number Type		13. Total Quantity		14. Unit Wt/Vol	
a. <b>RO, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, Pg II</b>						002 CM				K	
b.										EPA	
c.										STATE	
d.										EPA	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. <b>CW4539; ERG#171</b>						a. <input type="checkbox"/>					
b.						b. <input type="checkbox"/>					
15. Special Handling Instructions and Additional Information											
<b>Emergency - 732 548-8730 ; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR # 683363-2</b>						<b>1-20 yd<sup>3</sup></b> <b>1-30 yd<sup>3</sup></b>					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations.											
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>		Signature <i>Jack Harmon</i>				Mo. <b>10</b>		Day <b>03</b>		Year <b>03</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name <i>Eric Bixby</i>		Signature <i>Eric Bixby</i>				Mo.		Day		Year	
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name		Signature				Mo.		Day		Year	
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name		Signature				Mo.		Day		Year	

TRANSPORTER

FACILITY

# NYG 1163214

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



## HAZARDOUS WASTE MANIFEST

P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303009</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of		Information within heavy bold line is not required by Federal Law.					
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2000 Woodbridge Ave., Edison, NJ 08837</b>						A. <b>NYG 1163214</b>							
4. Generator's Telephone Number <b>(732) 321-4427</b>						B. Generator's ID <b>State</b>							
5. Transporter 1 (Company Name) <b>Prochold Cartage Inc</b>				6. US EPA ID Number <b>NJD034126164</b>		C. State Transporter's ID <b>1163214</b>							
7. Transporter 2 (Company Name)				8. US EPA ID Number		D. Transporter's Telephone <b>(732) 462-1901</b>							
9. Designated Facility Name and Site Address <b>CNA Chemical Services, Inc. 1135 Salmer Rd., Madison City, NY 14107</b>						E. State Transporter's ID							
10. US EPA ID Number <b>NYD094736679</b>						F. Transporter's Telephone ( )							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						G. State Facility ID							
a. <b>30, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2315, Pg II</b>						12. Containers Number Type <b>007 CN</b>		13. Total Quantity		14. Unit Wt/Vol <b>E</b>		I. Waste No. EPA <b>STATE 8007</b>	
b.												EPA STATE	
c.												EPA STATE	
d.												EPA STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above							
a. <b>CH4539; ERG0171</b>						a. <input checked="" type="checkbox"/> <b>L</b>							
b.						b. <input type="checkbox"/>							
15. Special Handling Instructions and Additional Information <b>Emergency - 1-202-544-8320 I send copy of completed manifest &amp; CD to Dana Slovins, 8473 Buske Rd., Stony Brook, VA 23852 Date out of Service: 5/4/98 SA # 623343-2 1-20 yds 1-30 yds</b>													
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.													
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>				Signature <i>Jack Harmon</i>				Mo. <b>04</b>		Day <b>03</b>		Year <b>03</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials													
Printed/Typed Name				Signature				Mo.		Day		Year	
18. Transporter 2 Acknowledgement of Receipt of Materials													
Printed/Typed Name				Signature				Mo.		Day		Year	
19. Discrepancy Indication Space													
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
Printed/Typed Name				Signature				Mo.		Day		Year	

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362



# FREEHOLD CARTAGE INC.

P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924



175 BARTOW MUN. AIRPORT  
BARTOW, FL 33830  
PHONE: (941) 533-4599  
FAX: (941) 533-1613

108 MONAHAN AVENUE  
DUNMORE, PA 18512  
PHONE: (570) 342-7232  
FAX: (570) 342-7367

350 PIGEON POINT ROAD  
NEW CASTLE, DE 19720  
PHONE: (302) 658-2005  
FAX: (302) 658-6229

156 DRIFTWOOD DRIVE  
EUTAWVILLE, SC 29048  
PHONE/FAX: (803) 492-9595

## MANIFEST

FCI EPA ID NO.:  
NJD054126164

**K 58444**

GENERATOR NAME/ADDRESS <b>BOZCOT INF J-2 PIR Region II</b> <b>UTCA NY 13502</b>		PHONE (AREA CODE) <b>732-321-4427</b> TRACTOR <b>567</b> TRAILER <b>294</b>		GENERATOR EPA ID NO. <b>NY0002249563</b>	
FCI REP. LOADING (PRINT) <b>Eric Bixby</b>		PROCEDURE <b>REMOVAL</b>		TIME AT GENERATOR (MILITARY TIME ONLY) <b>08:00</b> <b>20:45</b> ARRIVAL TIME DEPARTURE TIME	
BOX SPOTTED				BOX REMOVED <b>31192</b> <b>9498</b>	
COMMENTS OR DELAYS AT GENERATOR				EQUIPMENT USED	

BROKER:		STATE MANIFEST NO.: <b>03009</b>	
PO#:	WO#:		

(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	<b>See Manifest 03009</b>	<b>9</b>	<b>231</b>	<b>TTL</b>	<b>2</b>	<b>CM</b>	<b>50</b>	<b>7.5</b>	<b>B.75</b>	
2										
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION (I.E., IDENTIFICATION SHIPMENT OF A NON-HAZARDOUS NATURE WHICH DOES NOT HAVE TO BE MANIFESTED).

GENERATOR'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The wastes described above were consigned to the Transporter named. The Treatment, Storage or Disposal Facility can and will accept the shipment of hazardous waste, and has a valid permit to do so. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the generator is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvarado / ET</b>	GENERATOR'S SIGNATURE <b>X</b> <i>Kim Alvarado</i> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <b>1 / 1</b> MO. DAY YR.
---	--	--

TSDF NAME/ADDRESS <b>CDM</b> <b>MOBILE TR 24 14107</b>		PHONE (AREA CODE) <b>716-754-8231</b> TRACTOR TRAILER		TSDF EPA ID NO. <b>0400014736677</b>	
FCI REP. UNLOADING (PRINT)		PROCEDURE <b>DOMP</b>		TIME AT TSDF (MILITARY TIME ONLY) ARRIVAL TIME DEPARTURE TIME	
BOX SPOTTED				BOX REMOVED	
COMMENTS OR DELAYS AT TSDF				EQUIPMENT USED	
PLEASE PRINT NAME/TITLE		TSDF SIGNATURE <b>X</b>		DATE UNLOADED <b>1 / 1</b> MO. DAY YR.	

AR H-0257  
PC 944  
CT CT-HW-307  
DE DE-HW-203  
DE-SW-203  
IL SWH-1540

ME ME-HWT-47  
ME-WOT-47  
MD HWH-167  
96-OP-1765  
MA MA-294  
MN 61572

MO H-1490  
ND WH-429  
NH TNH-0047  
NJ S-2265  
15939  
NY NJ-113

NOVA SCOTIA, CANADA NSC 000 147  
OH UPW-0190713-0H  
OK 3358  
ONTARIO, CANADA A 840943  
PA PA-AH-0067

QUEBEC, CANADA QC-6ML-047  
RI RI-535  
TX 40705  
WI 11602

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator

**K 58444**

NYG 1163232

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple.

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303011</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.	
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163232</b> <b>B. Generator's ID</b> <b>SAME</b> <b>C. State Transporter's ID</b> <b>0994349 ME</b> <b>D. Transporter's Telephone</b> <b>732 462-1001</b> <b>E. State Transporter's ID</b> <b>F. Transporter's Telephone ( )</b> <b>G. State Facility ID</b> <b>H. Facility Telephone ( )</b> <b>716-754-8231</b>			
4. Generator's Telephone Number <b>(732) 321-4427</b>		6. US EPA ID Number <b>NYD054126164</b>		8. US EPA ID Number					
5. Transporter 1 (Company Name) <b>Freehold Cartage INC.</b>		7. Transporter 2 (Company Name)							
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>		10. US EPA ID Number <b>NYD094736679</b>							
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>RO, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2315, PG II</b>		12. Containers Number <b>2</b> Type <b>CM</b>		13. Total Quantity					
J. Additional Descriptions for Materials listed Above <b>a CW4539; ERG1171</b>						K. Handling Codes for Wastes Listed Above a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d <input type="checkbox"/>			
15. Special Handling Instructions and Additional Information <b>Emergency - 732-548-8730 ; Send copy of completed manifest &amp; CD to Dawn Blevins 8473 Haske Rd., Stony Creek, VA 23882 Date out of Service: 5/9/03 2-30yds SR # 683363-3</b>									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>		Signature <i>Jack Harmon</i>		Mo. <b>06</b> Day <b>03</b> Year <b>03</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name <b>ROBERT SMITH</b>		Signature <i>Robert Smith</i>		Mo. <b>06</b> Day <b>03</b> Year <b>03</b>			
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name		Signature		Mo. Day Year			
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name		Signature		Mo. Day Year					

GENERATOR

TRANSPORTER

FACILITY

NYG 1163232

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple.

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956203011</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of <b>1</b>		Information within heavy bold line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>ATTN: Jack Harrison USEPA Region II - Spasart Manufacturing 2690 Woodbridge Ave., Edison, NJ 08837</b>						A. <b>NYG 1163232</b>					
4. Generator's Telephone Number ( <b>732</b> ) <b>321-4427</b>						B. Generator's ID <b>5107</b>					
5. Transporter 1 (Company Name) <b>Freehold Cartage Inc.</b>						C. State Transporter's ID <b>0937591142</b>					
6. US EPA ID Number <b>NYD054126164</b>						D. Transporter's Telephone ( <b>732</b> ) <b>462-1901</b>					
7. Transporter 2 (Company Name)						E. State Transporter's ID					
8. US EPA ID Number						F. Transporter's Telephone ( )					
9. Designated Facility Name and Site Address <b>CHE Chemical Services, Inc. 1125 Balmer Rd. Model City, NY 14107</b>						G. State Facility ID					
10. US EPA ID Number <b>NYD094736679</b>						H. Facility Telephone ( ) <b>716-734-0231</b>					
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit	
						Number		Quantity		Wt/Vol	
a. <b>HQ, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2315, PG II</b>						<b>002</b>		<b>CA</b>		<b>E</b>	
b.										EPA	
c.										STATE <b>0007</b>	
d.										EPA	
										STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. <b>CM4539; ERO1171</b>						a. <b>L</b>					
b.						b.					
15. Special Handling Instructions and Additional Information <b>Emergency - 1-800-424-8802 Send copy of completed manifest &amp; CD to Dawn Blevins 8673 Husko Rd., Stony Creek, VA 23082 Date out of Service: 2/3/16 SL# 425563-3</b>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harrison, USEPA Region II OSC</b>						Signature <i>[Signature]</i>					
17. Transporter 1 Acknowledgement of Receipt of Materials						Mo. Day Year <b>06 03 03</b>					
Printed/Typed Name <b>Robert Smith</b>						Signature <i>[Signature]</i>					
18. Transporter 2 Acknowledgement of Receipt of Materials						Mo. Day Year <b>06 03 03</b>					
Printed/Typed Name						Signature					
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name						Signature					
						Mo. Day Year					

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**L 74856**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-7367156 Driftwood Drive  
Eutawville, SC 29048  
Phone: (803) 492-9595  
Fax: (803) 492-3350

SHIPPER NAME/ADDRESS <b>BOSSETT MANUF.</b>		PHONE <b>732-321-4427</b>		NYD0002249563	
UTICA, NY 13502		(AREA CODE)			
FCI REP. LOADING (PRINT) <b>Bob Smith</b>		PROCEDURE <b>REMOVE</b>		EQUIP. SPOTTED <b>748</b>	
		EQUIP. REMOVED <b>4445</b>		APPOINTMENT TIME :	
COMMENTS OR DELAYS AT SHIPPER		TIME AT SHIPPER <b>19:45</b>		(MILITARY TIME ONLY) <b>20:45</b>	
		ARRIVAL TIME		DEPARTURE TIME	
EQUIPMENT USED					

BROKER:		MANIFEST / DOCUMENT NO. <b>NYG-1163232</b>	
PO #:	WO #:		

(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	SEE MANIFEST	9	2315	II	2	CM	100	Y	Boo7	5
2										
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER.
---

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvesta / ET</b>	SHIPPER'S SIGNATURE <b>X</b> <i>Kim Alvesta</i>	DATE LOADED <b>6/3/03</b>
I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.		MO. DAY YR.

CONSIGNEE NAME/ADDRESS <b>CIUM</b>		PHONE <b>716-754-8231</b>		NYD0094736679	
MODEL CITY, NY 14107		(AREA CODE)			
FCI REP. UNLOADING (PRINT) <b>Bob Smith</b>		PROCEDURE		EQUIP. SPOTTED <b>748</b>	
		EQUIP. REMOVED <b>4445</b>		APPOINTMENT TIME :	
COMMENTS OR DELAYS AT CONSIGNEE		TIME AT CONSIGNEE :		(MILITARY TIME ONLY) :	
		ARRIVAL TIME		DEPARTURE TIME	
EQUIPMENT USED					

PLEASE PRINT NAME/TITLE	CONSIGNEE SIGNATURE <b>X</b>	DATE UNLOADED <b>6/4/03</b>
		MO. DAY YR.

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK 3358	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**L 74856**

NYG 1163259

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS  
**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212



Please type or print. Do not staple.

(Hazardous Waste Manifest 1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303013</b>		Manifest Doc. No.		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>APTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163259</b> <b>B. Generator's ID: SAME</b> <b>C. State Transporter's ID: ME0440456</b> <b>D. Transporter's Telephone: (732) 462-1001</b> <b>E. State Transporter's ID:</b> <b>F. Transporter's Telephone:</b> <b>G. State Facility ID:</b> <b>H. Facility Telephone: 716-754-8231</b>					
4. Generator's Telephone Number <b>(732) 321-4427</b>		6. US EPA ID Number <b>NYD054126164</b>									
5. Transporter 1 (Company Name) <b>Freehold Cartage Inc</b>		8. US EPA ID Number									
7. Transporter 2 (Company Name)											
9. Designated Facility Name and Site Address <b>Chemical Services 1135 Balmer Rd. Model City, NY 14107</b>		10. US EPA ID Number <b>NYD094736679</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit	
<b>a. RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b> <b>b.</b> <b>c.</b> <b>d.</b>						Number		Type		Quantity	
						002		CM		K	
						KRA					
						14. Unit		15. Waste No.			
						K		B007		EPA	
										STATE	
										EPA	
										STATE	
										EPA	
										STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. CW4539; EPC#171						a. <input type="checkbox"/> c. <input type="checkbox"/>					
b.						b. <input type="checkbox"/> d. <input type="checkbox"/>					
15. Special Handling Instructions and Additional Information											
<b>Emergency - 732 548-8730 ; Send copy of completed Manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR # 683363-4 2-30 yds</b>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations.											
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harmon, USPA Region II OSC</b>						Signature <i>Jack Harmon</i>					
						Mo. Day Year <b>06 03 03</b>					
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name <i>John Roush</i>						Signature <i>John Roush</i>					
						Mo. Day Year <b>06 03 03</b>					
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name						Signature					
						Mo. Day Year					
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name						Signature					
						Mo. Day Year					

NYG 1163259

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>RYD00224956303013</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.			
3. Generator's Name and Mailing Address <b>ATPA: Jack Harmon USPA Region II - Basset Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163259</b> <b>B. Generator's ID</b> <b>C. State Transporter's ID</b> <b>D. Transporter's Telephone (732) 462-1001</b> <b>E. State Transporter's ID</b> <b>F. Transporter's Telephone ( )</b> <b>G. State Facility ID</b> <b>H. Facility Telephone (716) 754-8231</b>					
4. Generator's Telephone Number (732) 321-4427		5. Transporter 1 (Company Name) <b>Frederick Cartman Inc</b>		6. US EPA ID Number <b>ED0054126164</b>							
7. Transporter 2 (Company Name)		8. US EPA ID Number									
9. Designated Facility Name and Site Address <b>CHI Chemical Services 1135 Balmer Rd. Model City, NY 14107</b>		10. US EPA ID Number <b>NYD094736679</b>									
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)											
a. <b>PO, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>				12. Containers Number <b>002</b>	Type <b>CM</b>	13. Total Quantity <b>1</b>	14. Unit Wt/Vol <b>K</b>	I. Waste No. EPA <b>5507</b> STATE			
b.								EPA STATE			
c.								EPA STATE			
d.								EPA STATE			
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above					
a. <b>CH4539; DRG171</b>				c.		a. <input checked="" type="checkbox"/>		c. <input type="checkbox"/>			
b.				d.		b. <input type="checkbox"/>		d. <input type="checkbox"/>			
15. Special Handling Instructions and Additional Information <b>Emergency - 1-800-424-8802 Send copy of completed Manifest &amp; CD to Dana Blevins, 8473 Maske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5-15-97 SL# 183313-4 2-30-97</b>											
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.											
Printed/Typed Name <b>Jack Harmon, USPA Region II OSC</b>				Signature <i>Jack Harmon</i>		Mo. <b>06</b>		Day <b>13</b>		Year <b>97</b>	
17. Transporter 1 Acknowledgement of Receipt of Materials											
Printed/Typed Name				Signature		Mo.		Day		Year	
18. Transporter 2 Acknowledgement of Receipt of Materials											
Printed/Typed Name				Signature		Mo.		Day		Year	
19. Discrepancy Indication Space											
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.											
Printed/Typed Name				Signature		Mo.		Day		Year	

P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924

N 43029

114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984

350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229

175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-1613

5533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732

108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-7367

40 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS BOBBERT MANUFACTURING 2810 Wood Bridge Ave Edison NJ 0883713502		PHONE 732 321 4427 (AREA CODE)			
TRACTOR 507		TRAILER 541		APPOINTMENT TIME :	
FCI REP. LOADING (PRINT) J. K. K... ..	PROCEDURE K... ..	EQUIP. SPOTTED	EQUIP. REMOVED 7110 7862	TIME AT SHIPPER 19:45 ARRIVAL TIME	(MILITARY TIME ONLY) 21:45 DEPARTURE TIME
COMMENTS OR DELAYS AT SHIPPER				EQUIPMENT USED	

BROKER:		MANIFEST / DOCUMENT NO.
PO #:	WO#:	

[illegible]

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <u>Khan Alwaleh, P/T</u>	SHIPPERS SIGNATURE X <u>Kin Alwaleh</u> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <u>6/3/13</u> MO. DAY YEAR
---	---	--

CONSIGNEE NAME/ADDRESS 66003 Bulmer Rd 11301 Arlington, VA 22204		PHONE (AREA CODE) 507		TRAILER 34'		APPOINTMENT TIME 10:00	
FCI REP. UNLOADING (PRINT) 1	PROCEDURE	EQUIP. SPOTTED	EQUIP. REMOVED		TIME AT CONSIGNEE (MILITARY TIME ONLY) ARRIVAL TIME: 10:00 DEPARTURE TIME:		
COMMENTS OR DELAYS AT CONSIGNEE					EQUIPMENT USED		

PLEASE PRINT NAME/TITLE	CONSIGNEE SIGNATURE	DATE UNLOADED
	X _____	____/____/____ MO. DAY YEAR

AR H-0257

CT CT-HW-307

DE DE-HW-203

DE-SW-203

IL UPW-0190713-OH

MA MA-294

MD HWH-167

2001-OPV-2335

ME ME-HWT-47

ME-WOT-47

MI UPW-0190713-OH

MN UPW-0190713-OH

MO H-1490

ND WH-429

NH TNH-0047

NJ S-2265

NJ 3-2263  
15939

NY NJ-113

OH UPW-0190713-OH

OK UPW-0190713-OH

ONTARIO, CANADA A 840943.

PA PA-AH-0067

QUEBEC, CANADA      QC-6ML-047

RI RI-535

TX 40705

TX 40705  
WI 11602

WV. UPW-0190713-OH

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDf  
Gold - Retained by Generator

N 43029

NYG 1163277

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



HAZARDOUS WASTE MANIFEST  
P.O. Box 12820, Albany, New York 12212

Please type or print. Do not staple.

(Hazardous Waste Manifest-1/28/98)

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956303015</b>		Manifest Doc. No. <b>1</b>		2. Page 1 of 1		Information within heavy bold line is not required by Federal Law.	
3. Generator's Name and Mailing Address <b>ATTN: Jack Harmon USEPA Region II - Bossert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						A. <b>NYG 1163277</b>			
4. Generator's Telephone Number (732) <b>321-4427</b>						B. Generator's ID <b>SAME</b>			
5. Transporter 1 (Company Name) <b>Freshhold Cartage Inc.</b>				6. US EPA ID Number <b>NJD054126164</b>		C. State Transporter's ID <b>044051C ME</b>			
7. Transporter 2 (Company Name)				8. US EPA ID Number		D. Transporter's Telephone (732) <b>462-1001</b>			
9. Designated Facility Name and Site Address <b>CWM Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>						E. State Transporter's ID			
10. US EPA ID Number <b>NYD094736679</b>						F. Transporter's Telephone ( )			
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number) <b>a. RQ, Waste Polychlorinated biphenyls, solid mixture, 9, UN 2315, PG II</b>						G. State Facility ID			
12. Containers Number Type <b>001 CM</b>						13. Total Quantity		14. Unit Wt/Vol <b>K</b>	
I. Waste No. EPA <b>BO07</b>									
STATE									
EPA									
STATE									
EPA									
STATE									
EPA									
STATE									
J. Additional Descriptions for Materials listed Above <b>a. CW4539: ERG#171</b>						K. Handling Codes for Wastes Listed Above <b>a</b>			
b						b			
15. Special Handling Instructions and Additional Information <b>Emergency - 732 548-8737; Send copy of completed manifest &amp; CD to Dawn Blevins, 8473 Huske Rd., Stony Creek, VA 23882</b> <b>Date out of Service: 5/9/03 SR# 683363-5 1-30yd<sup>3</sup></b>									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>						Signature <i>Jack Harmon</i>			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name <b>WAYNE YEAGER</b>						Signature <i>Wayne Yeager</i>			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name						Signature			
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name						Signature			



NYG 1163277

STATE OF NEW YORK  
DEPARTMENT OF ENVIRONMENTAL CONSERVATION  
DIVISION OF SOLID & HAZARDOUS MATERIALS



**HAZARDOUS WASTE MANIFEST**  
P.O. Box 12820, Albany, New York 12212

(Hazardous Waste Manifest 1/28/98)

Please type or print. Do not staple

In case of emergency or spill immediately call the National Response Center (800) 424-8802 and the NYS Department of Environmental Conservation (518) 457-7362

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator's US EPA ID No. <b>NYD00224956103015</b>		Manifest Doc. No.		2. Page 1 of <b>1</b>		Information within heavy bold-line is not required by Federal Law.							
3. Generator's Name and Mailing Address <b>ATM: Jack Harmon USEPA Region II - Bousert Manufacturing 2890 Woodbridge Ave., Edison, NJ 08837</b>						<b>A. NYG 1163277</b> <b>B. Generator's ID</b> <b>C. State Transporter's ID</b> <b>D. Transporter's Telephone (- 732) 452-1501</b> <b>E. State Transporter's ID</b> <b>F. Transporter's Telephone (- )</b> <b>G. State Facility ID</b> <b>H. Facility Telephone (- )</b> <b>716-754-8231</b>									
4. Generator's Telephone Number <b>(732) 321-4427</b>		6. US EPA ID Number <b>NYD054126164</b>													
5. Transporter 1 (Company Name) <b>Freehold Cartage</b>		8. US EPA ID Number													
7. Transporter 2 (Company Name)		10. US EPA ID Number <b>NYD094736679</b>													
9. Designated Facility Name and Site Address <b>CMA Chemical Services, Inc. 1135 Balmer Rd. Model City, NY 14107</b>															
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total		14. Unit					
<b>a. 20, Waste Polychlorinated Biphenyls, solid mixture, 9, UN 2815, PG II</b> <b>b.</b> <b>c.</b> <b>d.</b>						Number		Type		Quantity		Wt/Vol		1. Waste No.	
						001		CH				R		EPA	
														STATE 8007	
														EPA	
														STATE	
J. Additional Descriptions for Materials listed Above						K. Handling Codes for Wastes Listed Above									
<b>a. CH4539; 1801171</b>						<b>a. 2</b>									
<b>b.</b>						<b>b.</b>									
15. Special Handling Instructions and Additional Information <b>Emergency - 781-543-2121; Send copy of completed manifest &amp; CD to Dave Slovins, 3473 Busite Rd., Stony Creek, VA 23382</b> <b>Date out of Service: 5/1/98</b>															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and state laws and regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.															
Printed/Typed Name <b>Jack Harmon, USEPA Region II OSC</b>				Signature <i>[Signature]</i>				Mo. Day Year <b>90 0 30 3</b>							
17. Transporter 1 Acknowledgement of Receipt of Materials															
Printed/Typed Name <b>WAYNE YOUNG</b>				Signature <i>[Signature]</i>				Mo. Day Year <b>90 0 30 3</b>							
18. Transporter 2 Acknowledgement of Receipt of Materials															
Printed/Typed Name				Signature				Mo. Day Year							
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.															
Printed/Typed Name				Signature				Mo. Day Year							

**FREEHOLD CARTAGE INC.**P.O. BOX 5010 • FREEHOLD, NJ 07728-5010  
(732) 462-1001 • FAX (732) 308-0924**BILL OF LADING**  
FCI EPA ID NO. NJD054126164**N 46462**114 Schoolground Rd.  
Branford, CT 06405  
Phone: (203) 483-5964  
Fax: (203) 483-5984350 Pigeon Point Road  
New Castle, DE 19720  
Phone: (302) 658-2005  
Fax: (302) 658-6229175 Bartow Mun. Airport  
Bartow, FL 33830  
Phone: (863) 533-4599  
Fax: (863) 533-16135533 Dunham Road  
Maple Heights, OH 44137  
Phone: (330) 835-3473  
Fax: (330) 835-3732108 Monahan Avenue  
Dunmore, PA 18512  
Phone: (570) 342-7232  
Fax: (570) 342-736740 Boulevard St.  
Sumter, SC 29150  
Phone: (803) 773-2611  
Fax: (803) 773-2942

SHIPPER NAME/ADDRESS <b>USEPA</b> <b>Bossert Manuf.</b> <b>Edison NJ</b>		PHONE <b>732 321-4427</b> (AREA CODE)		N 4 0 0 0 2 2 4 9 5 6 3	
FCI REP. LOADING (PRINT) <b>Wayne Yeager</b>		PROCEDURE <b>Removal</b>	EQUIP. SPOTTED	EQUIP. REMOVED <b>9923</b>	APPOINTMENT TIME :
COMMENTS OR DELAYS AT SHIPPER				EQUIPMENT USED	

BROKER:			MANIFEST / DOCUMENT NO.							
PO #:			WO#:							
(X) HM	PROPER U.S. D.O.T. SHIPPING NAME	U.S. D.O.T. HAZARDOUS CLASS	NA/UN/NO.	PACKING GROUP	NO. CONT.	CONT. TYPE	NET QUANTITY	UNIT MEASURE	WASTE NO.	FORM
1	<b>See Manifest</b>									
2										
3										

SPECIAL HANDLING INSTRUCTIONS INCLUDING CONTAINER EXEMPTION NUMBER										
--	--	--	--	--	--	--	--	--	--	--

SHIPPER'S CERTIFICATION: This is to certify that the above named materials are properly classified, described, packaged, marked and labeled and are in proper condition for transportation according to the applicable regulations of the Department of Transportation, U.S. EPA and the State. The materials described above were consigned to the Transporter named. The consignee can and will accept the shipment and has a valid permit to do so if required. I certify that the foregoing is true and correct to the best of my knowledge.

Payment to the contractor for waste removal does not constitute payment to the carrier and if the contractor does not pay the carrier, the shipper is obligated to pay the agreed rate offered to the contractor.

PLEASE PRINT NAME/TITLE <b>Kim Alvestad / ET</b>	SHIPPER'S SIGNATURE X <b>[Signature]</b> I HAVE READ THE ABOVE AND UNDERSTAND AND AGREE TO ALL OF ITS CONTENT.	DATE LOADED <b>6 / 3 / 03</b> MO. DAY YEAR
---	--	--

CONSIGNEE NAME/ADDRESS <b>Cum</b> <b>Mud City NY 14107</b>		PHONE <b>716 751-8231</b> (AREA CODE)		N 4 0 0 9 4 7 3 6 2 7 5	
FCI REP. UNLOADING (PRINT)		PROCEDURE	EQUIP. SPOTTED	EQUIP. REMOVED	APPOINTMENT TIME :
COMMENTS OR DELAYS AT CONSIGNEE				EQUIPMENT USED	

PLEASE PRINT NAME/TITLE	CONSIGNEE SIGNATURE X <b>[Signature]</b>	DATE UNLOADED <b>/ /</b> MO. DAY YEAR
-------------------------	---	---

AR H-0257	MD HWH-167	MO H-1490	OH UPW-0190713-OH	TX 40705
CT CT-HW-307	2001-OPV-2335	ND WH-429	OK UPW-0190713-OH	WI 11602
DE DE-HW-203	ME ME-HWT-47	NH TNH-0047	ONTARIO, CANADA A 840943	WV UPW-0190713-OH
DE-SW-203	ME-WOT-47	NJ S-2265	PA PA-AH-0067	
IL UPW-0190713-OH	MI UPW-0190713-OH	15939	QUEBEC, CANADA QC-6ML-047	
MA MA-294	MN UPW-0190713-OH	NY NJ-113	RI RI-535	

White - FCI Original  
Yellow - FCI Billing  
Blue - FCI Office/Customer  
Green - Retained by TSDF  
Gold - Retained by Generator**N 46462**